File No: 1241877-2024

FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

- 1 Name of Officer
- 2 Name of School
- 3 Location with name of Education
- Classification of building as specified in column 4 of application for fitness certificate and size
- Shylaja.K.P
- St.Ann's Public School, Eloor
- Eloor Aluva, Aluva
- Three Storied Building Ground Floor

Classroom	1x7.20x6.00x3.70m
Chemistry Lab	1x12.23x7.20X3.70m
Reception, Library	1x12.23x7.20x3.70m
Store.	2x 3.4 x 2.88x3.70m

First Floor

Class room	3x6x7.20x3.70m
Staff room	1x300x7.20x3.70m
Computer room	1x12.23x7.20x3.70m
Physics Lab	1x7.20x6.00x3.70m
Botony lab	1x12.23x7.20x3.70m
Room for Guide	1x2.40x2.88x3.70m
Store for Lab	2x3.48x2.88x3.70m

Second Floor

Class room	5x7.20x6.00x3.70m
Class room	1x7.20x6.00x3.70m
Store for lab	2x3.48x2.88x3.70m
Class room	1x3.00x7.20x3.70m
Biology lab	1x12.23x7.20x3.70m
Room	1x2.40x2.88x3.70

- Period of which the certificate is issued
- Nature of defect if any
 - Foundation and basement a)
 - b) Superstructure
 - c) Doors and windows
 - d) Wood work wrought & put up
 - e) Roof
 - f) Flooring
 - Miscellaneous (Cracks etc.)
- Any major defects noticed which will render the building unsafe in any manner
- Whether the maintenance works have been done properly
- Whether the structure is sound or not for conducting classes

- For the academic year 2024-25
- Nil
- Yes
- - Sound under normal weather condition

Note

1: The stability of the structure should be examined also with reference to location, attitude, intensity of wind, exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished/separately with the certificate.

Place: Eloor

Date: 25..05.2024



Signature:

Designation
ക്ഷെല്യാ കെ. പി.
PEN No.. 641226
അസിസ്റ്റന്റ് എഞ്ചിനിയർ
LID & EVV
എലൂർ നഗരസഭ